

Fig. 1








Fig. 2

FIG. 2

*Fig. 3*

*Fig. 4A**Fig. 4B*

FOI 90-62864860

*Fig. 5*

240

New Inspection Inspection Info Comments

248 → INSPECTION INFO

242

- 1 Customer Name
- 2 Customer Phone
- 3 Customer Address
- 4 Customer City
- 5 Customer State
- 6 Customer Zip 246
- 7 Inspector Name
- 8 Inspection Date
- 9 Comments

244

Customer Name:	Bob Smith
Customer Phone:	555-1212
Customer Address:	123 Main St.
Customer City:	Seattle
Customer State:	
Customer Zip:	
Inspector Name:	
Inspection Date:	
Comments:	

Fig. 6

260

270 → INSPECTION INFO

Page Up ▲

- 1 Customer Name
- 2 Customer Phone
- 3 Customer Address
- 4 Customer City
- 5 Customer State
- 6 Customer Zip 272
- 7 Inspector Name
- 8 Inspection Date
- 9 Comments

Page Down ▼

264

262 268 266

New Inspection Inspection Info

Fig. 7




Fig. 8

09879829-06.1.01

308

<i>JOHN</i> INVENTORY PARTS ASSEMBLE INTAKE LUBRICATE CORE
<i>JAMIE</i> LUBRICATE CORE INSTALL INTAKE VERIFY CHARGE
<i>MAX</i> LUBRICATE CORE INSTALL INTAKE VERIFY CHARGE
<i>CAROL</i> INSTALL INTAKE VERIFY CHARGE RUN DIAGNOSTICS
INVENTORY ASSEMBLE LUBRICATE INSTALL VERIFY RUN

Fig. 9

09879829.06.1101